


MODEL TC1966D

## **CORRECTION NOTICE**





R356, R357 and C181 were labeled incorrectly in the REVISION SUFFIX B service manual for TC1966D (PUB. NO. 37-92). For correct part description, see below.

REF. NO. <u>∧</u> R356	INCORRECT					CORRECT				
	PART. NO.	D	DESCRIPTION			PART. NO.	DESCRIPTION			
	R3K181561J	R, FUSE	560 (	OHM 2V	W	R3K181561J	R, METAL	560	OHM	1W
<b>∆</b> R357	R3K181221J	R, FUSE	220 (	OHM 1/	/2W	R3K181221J	R, METAL	220	OHM	1W
C181	CHGTSL4G1J	CC	22 I	PF 50	VC	CHGTSL4H1J	CC	22	PF	50V

Please file this correction notice with the original version.

SERVICE PUBLICATION

**#119-92**